



# www.Cabrio-Heckscheibe.de

# Instructions

Repair Kit for Convertible Top Hood



Das Grundproblem ist das sich Pos.1 nicht weitgenug an Pos. 2 bewegt, das wird mit dem Reparatur-Kit behoben.

The main problem is that pos.1 doesn't move far enough towards pos.2. Our repair-kit solves this problem.



Pos.1 and 2 have to be connected through our repair-kit



The expander has to be placed on the inside like shown on the photo



The same at this position



Thread the expander over the struts and push on the crimp



Now squeeze the crimp in the middle like shown

